

**CAMERON BALLOONS LTD and THUNDER & COLT**

**SERVICE BULLETIN: SB9**

**Title:** Return to Service of Titanium Propane Cylinders.

**Parts affected:** Titanium propane cylinders types:  
  
CB2380, serial numbers BT0005 onwards.  
CB2383, serial numbers BT0001 to BT0010, BT0012 to BT0014,  
BT0016 to BT0033 onwards.

**Reason** Embodiment of Cameron Modification C274 Issue 2.

**Classification:** Recommended.

**Compliance:** Receipt of cylinder release to service following rework.

**Note:** An 'S' suffix to the part number denotes embodiment of Cameron Modification C274 Issue 2. The 'S' suffix is engraved on cylinder identification plate.

**Accomplishment Instructions.** Cylinder Modification carried out by Cameron Balloons. A check for the presence of the above noted Cameron-applied suffix must be made before use.

**If in doubt please contact the factory.**

**Cameron Balloons Ltd /Thunder and Colt  
St John's Street  
Bedminster  
Bristol BS3 4NH**

**Tel +44 (0)117 9637216, fax +44 (0)117 9661168**